NO. OF COPIES RECEIVED	12	-1				F 0 +			
DISTRIBUTION						Form C-103 Supersedes Old			
SANTA FE					C-102 and C-103				
				Effective 1-	1-65				
U.S.G.S.	+		OCT	5a. Indicate Type of Lease					
LAND OFFICE	+ +		0.9.			State 🛨	Fee		
OPERATOR	+ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$	-		5. State Oil & Gas Lease No.					
						K-5696			
(DO NOT USE THIS F USI	SUND	RY NOTICES	AND REPORTS C	BACK TO A DIFFE	RENT RESERVOIR.				
1. OIL GAS WELL WEI		OTHER-	Dry Ho	1 e		7. Unit Agreeme	ent Name		
2. Name of Operator H. N. Sweeney 3. Address of Operator P. O. Box 1582 - Roswell, New Mexico 88201							8, Farm or Lease Name		
							State "Z"		
							9. Well No.		
							1		
4. Location of Well						10. Field and Pool, or Wildcat			
UNIT LETTER 0	•	660 FEE	T FROM THE SOUL		1980 FEET FRO	Wildca	it		
THE Bast		rion <u>36</u>	TOWNSHIP78	RANGE	29E NMPN				
15. Elevation (Show whether DF, RT, GR, etc.)									
	<u>11111</u>	111111	4174	' GR		Chaves			
15.	Check	Appropriate	Box To Indicate	Nature of No	tice, Report or O	ther Data			
NOTI		INTENTION .				T REPORT OF	·:		
PERFORM REMEDIAL WORK			PLUG AND ABANDON	REMEDIAL WO	RK	ALTE	RING CASING		
TEMPORARILY ABANDON				COMMENCE DR	ILLING OPNS.	PLUG	AND ABANDONMENT		
PULL OR ALTER CASING			CHANGE PLANS	CASING TEST	AND CEMENT JOB				
				OTHER	<u> </u>				
OTHER			[<u></u>					
			· · · · · · · · · · · · · · · · · · ·	-1					

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and Abandoned 9-26-67 as follows:

Set 50 sack cement plug from 3250 to 3390 and 10 sack plug at surface. Set regulation marker and cleared location.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	N.M. Storeneng	TITLE	Operator	DATE 10-3-6	1
APPROVED BY	Ja f. A.	TITLE	<u>त्र २ १३३२७ वन्त्र है</u>	DATE	