

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-00422
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name White Ranch
8. Well No. 3
9. Pool name or Wildcat White Ranch Mississippian (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	RECEIVED CD - ARTESIA
2. Name of Operator C.W. Trainer	
3. Address of Operator P.O. Box 754, Midland, TX 79702	
4. Well Location Unit Letter M : 980 Feet From The South Line and 660 Feet From The West Line Section 34 Township 11-S Range 29# NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3778' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-16-01 Set 5-1/2" CIBP @ 8240', dump bail 3 sx cmt. on CIBP.
1-16-01 Mix mud & Circulate hole.
1-17-01 Perf 4 holes @ 6750', pressure up to 1000 PSI, held. Spot 25 sx cmt. @ 6800', Tag @ 6611'.
1-18-01 Perf 4 holes @ 5742', set pkr @ 5500', pressure up to 1000 PSI, held. Spot 25 sx cmt. @ 5800', tag @ 5621'.
1-18-01 Perf 4 holes @ 3399', set pkr @ 3150', pressure up to 1000 PSI, held. Spot 25 sx cmt. @ 3450', tag @ 3270'.
1-18-01 Perf 4 holes @ 2196', set pkr @ 1950', pressure up to 1000 PSI, held. Spot 25 sx cmt. @ 2246'.
1-19-01 Tag plug @ 1936'.
1-19-01 Perf 4 holes @ 130', pump 35 sx cmt. to Surface out of 8-5/8" csg, leave 5-1/2" csg. full of cmt.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 2-02-01
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 530-0907

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE JAN 27 2000
CONDITIONS OF APPROVAL, IF ANY: