

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

NOV 3 1982

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- ARTESIA, OFFICE		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Paul Slayton		5. State Oil & Gas Lease No. V-131
3. Address of Operator P. O. Box 1936 Roswell, New Mexico 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER E 1650 FEET FROM THE N LINE AND 990 FEET FROM THE W LINE, SECTION 5 TOWNSHIP 8 S RANGE 27 E NMPM.		8. Farm or Lease Name Sinclair State
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. # 1
		10. Field and Pool, or Wildcat Acme S A
		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-2-82 Drop 200 gal. sodium citrate down tubing to loosen gypsum scale.
9-30-82 Pull tubing and sand pump to old T.D. of 1950'
10-1-82 Set 210 bbl. tank & hook up.
10-4-82 Run tubing, rods & pump.
10-5-82 Space out pump, install new motor & panel.
Waiting on electric man.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Slayton TITLE operator DATE 11/02/82

PROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE NOV 4 1982

CONDITIONS OF APPROVAL, IF ANY: