


STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2085
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78



5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. N.A.
7. Unit Agreement No. N.A.
8. Name of Lease Holder Isler
9. Well No. 2
10. Field and Pool, or Locality L E Ranch-San Andres
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER: Re-Entry of T.A. well

Name of Operator: BILL G. ISLER 505-625-9154

Address of Operator: 123 Three Cross, Roswell, New Mexico 88201

Location of Well: UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 21 TOWNSHIP 10S RANGE 28E NEARLY

15. Elevation (Show whether DF, RT, GR, etc.)
3733 Tubing Head

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This temporarily abandoned oil well was cleaned out to the previous total depth of 2374'. Ran 2-3/8" tubing to 2345'. Treated perforations 2303' to 2348' with acid. Ran rods and pump tested. Produced 99% water. Pulled tubing and rods.

Propose to:

1. Plug by filling casing from TD to surface with approximately 7-1/2 cu. yds. of Redi-Mix grout.
2. Erect dry hole marker.
3. Condition location to satisfaction of the surface owner.
4. File Subsequent Report of Abandonment and Well Log after the work has been accomplished.

* But hole dry before dumping red mix or pump cement to bottom thru tubing will also need to fill B&E Casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNED Jerry H. Long TITLE Agent DATE 8/31/83
APPROVED BY Mike Wilson TITLE OIL AND GAS INSPECTOR DATE SEP 15 1983
CONDITIONS OF APPROVAL, IF ANY: * As Noted Above