

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY  
JAN 25 1984  
O. C. D.  
ARTESIAN OFFICE

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.  
N.A.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT ARTESIAN OFFICE)  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSAL

1. OIL WELL ☐ GAS WELL ☐ OTHER- Re-entry

Name of Operator: BILL G. ISLER ✓

Address of Operator: 123 Three Cross  
Roswell, New Mexico 88201

4. Location of Well  
UNIT LETTER M 330' FEET FROM THE South LINE AND 330' FEET FROM  
THE West LINE, SECTION 21 TOWNSHIP 10S RANGE 28E N.M.P.M.

7. Unit Agreement Name: N.A.

8. Farm or Lease Name: Isler

9. Well No.: 2

10. Field and Pool, or wildcat: L.E. Ranch-San Andres

11. Elevation (Show whether DF, RT, GR, etc.): 3733' Tubing Head

12. County: Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Re-entry was unsuccessful.

Plugged well as follows:

1-16-84 Set 50 sacks cement plug from PB depth of 2352' to 2039'.  
Cut off 4-1/2" casing at 1165' and pulled.

1-20-84 Loaded hole with gel mud.  
Spotted 30 sacks cement plug 1800' to 1700'. Tagged plug.  
Spotted 35 sacks cement plug 1203' to 952'. Tagged plug.  
Spotted 70 sacks cement plug 590' to 330'. Tagged plug.  
Spotted 10 sacks cement plug 60' to surface.  
Installed marker and cleaned location.

Best FD-2  
1-20-84  
PCH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: Jerry W. Long TITLE: Agent DATE: January 23, 1984

APPROVED BY: Larry Brooks TITLE: Geologist DATE: 1-30-84

CONDITIONS OF APPROVAL, IF ANY: