STATE OF NEW MEXICO . ENERGY AND MINERALS DEPARTMENT	
DIL CONSERVATIONEDIMISION DISTRIBUTION P. O. BOX 2088 SANTA FE, NEW MEXICO \$750984	Form C-103 Revised 10-1-78
U.S.O.S. LAND OFFICE OFENATOR OFFICE ARTESIA, OFFICE	State Oil & Gas Lease No.
	N.A.
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS SOUTH FOR PROPOSALS TO GRILL OR TO DEEPLY OR PLEASE TO A DIFFERENT RESERVOIR.	7, Unit Agreement Name
OIL CAS WELL OTHER- RE-Entry Chame of Operator	N.A. 8. Form or Lease Rane
BILL G. ISLER / 1. Address of Operator 123 Three Cross Roswell, New Mexico 88201	Isler 9. Well No. 1
UNIT LETTER A 330 FEET FROM THE NORTH LINE AND 330 FEET FRO	L.E. Ranch-San Andres
East LINE, SECTION 29 TOWNSHIP 10 S RANGE 28 E NMPN	
15. Elevation (Show where DF, RT, GR, etc.) 3741' Tubing Head	12. County Chaves
Check Appropriate Box To Indicate Nature of Notice, Report or O NOTICE OF INTENTION TO: SUBSEQUEN	ther Data IT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TOMMENCE DRILLING OPHS.	ALTERING CASING PLUG AND ABANDONMENT
Amended Intent to Abandon	
17. Describe Proposed or Completed Operations (Clearly state all pertinent excells, and give pertinent dates, including	se estimated date of starting any proposed
work) SEE RULE 1103.	
Propose to plug and abandon as follows:	
Plug No.1 - 2039' to 2375' from TD to a point 50' a highest perforation.	above
Plug No.2 - Perforate 5-1/2" at 1189' and leave 100 and outside of casing across top of Que	
Plug No.3 - Perforate 5-1/2" casing at 542', which base of Salt. Circulate cement to surfop of plug in 9-1/2" casing to be 50' Salt and 32' above 8-5/8" casing shoe.	face in annulus.
Plug No.4 - 5 Sacks in 5-1/2" casing at surface. and clean up location.	Install marker
	·
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Jerry H. Long Hill Agent	January 7, 1984
JERRY W. LONG Original Signed By Leslie A. Clements Supervisor District II	JAN 1 8 1984