

NO. OF COPIES RECEIVED	✓
DISTRIBUTION	
SANTA FE	✓
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	✓

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 15 1974

**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>H. E. Prince</b>	8. Farm or Lease Name <b>Beadle</b>
3. Address of Operator <b>606 N. Atkinson, Roswell, N. Mex. 88201</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>I</b> <b>2325.5</b> FEET FROM THE <b>S</b> LINE AND <b>330</b> FEET FROM THE <b>E</b> LINE, SECTION <b>5</b> TOWNSHIP <b>7S</b> RANGE <b>26E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Slaughter-San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3600 GR</b>	12. County <b>Chaves</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Plug and abandon as follows:**  
**Well depth 1069 ft.**  
**Run 15 sacks of cement from 1069 back to 888.10'**  
**Out casing at 670.50' from surface**  
**Run mud from 888.10 back to 155'**  
**Run 100' cement plug from 155' back to 55', 50' in and 50' out of surface casing.**  
**Run mud from 55' back to 10'**  
**Run cement from 10' back to surface and set marker**  
**Clean debris from site**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. E. Prince TITLE Owner DATE 10/10/74

APPROVED BY W. A. Gressett OIL AND GAS INSPECTOR DATE OCT 23 1974  
 CONDITIONS OF APPROVAL, IF ANY: Plugging  
 Notify N.M.O.C.C. in sufficient time to witness