

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 15 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">O. C. C. ARTESIA, OFFICE</p> <p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator H. E. Prince</p> <p>3. Address of Operator 606 N. Atkinson, Roswell, New Mexico 88201</p> <p>4. Location of Well UNIT LETTER P 990 FEET FROM THE W LINE AND 990' FEET FROM THE S LINE, SECTION 4 TOWNSHIP 7S RANGE 26 E NMPM.</p>	<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name BRADLE</p> <p>9. Well No. 8</p> <p>10. Field and Pool, or Wildcat Slaughter-San Andres</p>	<p>11. Elevation (Show whether DF, RT, GR, etc.) 3599 GR</p> <p>12. County Chaves</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon as follows:
Well depth 1045'
Run 15 sacks of cement from 1045' back to 864.10
Run mud from 864.10' back to 110' 160
Run cement from 110' back to surface 60' in and 90' out of surface pipe
Set marker 160
Clean debris from site

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. E. Prince TITLE OWNER DATE 10-10-74

APPROVED BY W. A. Gussert TITLE OIL AND GAS INSPECTOR DATE OCT 23 1974

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness plugging