

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons. Div
1301 W. Grand Ave.
Artesia, NM 88210

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

C/SI

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

Name of Operator

M.E.W. Enterprise

Address

300 South Kentucky Roswell/NM 88203

Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit L 1650 FSL 331 FWL S34, T6S, R4E

Phone No. (include area code)

505-627-3043

Lease Serial No.

LC-068132

If Indian, Allottee or Tribe Name

If Unit or CA/Agreement, Name and/or No.

Well Name and No.

Crandell Phillips #1

API Well No.

30-005-10052

Field and Pool, or Exploratory Area

Linda San Andres

County or Parish, State

Chaves NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

8 5/8 surface @ 105' cmt w/ 50 sxs
4 1/2 set 1210' w/ 50 sxs
perforation's 1148-1168

MIRU WSK. pull Rods & pump, pull lbs
Fill cased hole from 1210' to 1100' w/ sand
Dump Bail 35' cmt to 1065', Displace

hole w/ Brine, cut off on part 4 1/2 csg at 105' spot 100' cmt plus
pull out of hole & pump 20' surface plug. Install Dry hole marker,
cut off anchors & Remove Production Eqp.

Starting Date shall be AS SOON AS I CAN Accepted for record - NMOCD

This well is being plugged due to no SWD in Area

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Russell Whitel

Signature

Russell Whitel

Title

Owner

Date

10-30-01

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Please see attached for amended
plugging procedures previously approved 11/9/01

RECEIVED

2002 JAN 28 AM 10:26

BUREAU OF LAND MGMT
ROSWELL, NM 87701

Amended Plugging Procedures

1. Fill hole from 1210' to 1100' with sand.
2. Place 100' cement plug on top of sand and tag
3. Set 100' cement plug from 1000' to 900'
4. Perforate 4 ½" casing at 150' and squeeze cement to surface.
5. Set cement plug inside 4 ½" casing from 150' to surface.