

400

**DRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to deepen or re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

OCD - ARTESIA

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

M. E. W. Enterprise

3a. Address

300 South Kentucky - Roswell, NM 88201

3b. Phone No. (including area code)

(505)627-2065

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter I - Sec 27-07S-26E

5. Lease Designation and Serial No.

NMLC067811A

6. If Indian, Allottee of Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

Dale Federal

8. Well Name and No.

001

9. API Well No.

30-005-10054

10. Field and Pool, or Exploratory Area

Leslie Springs

11. County or Parish, State

Chaves, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug & Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on the file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

CASING 190'  
8 5/8 100'  
4 1/2 1530  
perfs 1498-1530

MFRU WSK, pull production app. Dump sand across perfs to 1450', dump bail 38' cmt. Displace hole w/ Gald brine, perfs 100' pump 100' cmt plug, pull out of hole pump 50' surface plug, Install dry hole

marker & clean location

Place 100' cmt. plug on top of Sand & TAG.

Place 100' cmt plug from 950' - 850' inside 4 1/2" CSG.

Perf. 4 1/2" CSG @ 240' & sg. cmt + 140' & place 100' plug in 4 1/2" from 240' - 140'

Set 50' surface plug.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Russell Whited

Signature

Title

Owner - Operator

Date

01-26-02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

C. E. by

Title

P. E.

Date

1/29/02

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the

Office

which would entitle the

RFO

Accepted for record

Title

only

FEB 5 2002

and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements.

RECEIVED

2002 JAN 28 AM 10:28

BUREAU OF LAND MANAGEMENT  
PORTLAND OFFICE