

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-068127

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Linda San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S 33, T 6 S, R 26 E

12. COUNTY OR PARISH

Chaves

13. STATE

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER
2. NAME OF OPERATOR
H. E. Prince
3. ADDRESS OF OPERATOR
606 N. Atkinson, Roswell, New Mexico, 88201
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit Letter O - 330' from W. Line
1650' from E. Line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3624 G R

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and abandon well as follows:

Well Depth 1148 ft.

Run 15 sacks of cement from 1148 ft. back to 966.10 ft.

Cut casing at 750 ft. from surface.

Run mud from 966.10 back 152 ft.

Run 100' cement plug 50' in and 50' out of surface pipe.

~~XXXXXXXXXXXXXXXXXXXX~~

Run mud from 52' back to 10' run cement to surface and set marker.

Clean debris from site.

RECEIVED
MAR 25 1975
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

H. E. Prince

TITLE

Owner

DATE

3-20-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side