

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLIC
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

FED. LG-068127

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FEDERAL

9. WELL NO.

Fed. #3

10. FIELD AND POOL, OR WILDCAT

LINDA SAN ANDRES

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S.33-T6S-R26E

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2. NAME OF OPERATOR H. E. Prince ✓	3608 GR
3. ADDRESS OF OPERATOR 606 N. Atkinson, Roswell, New Mexico, 88201	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter K - 2328.9' From W. Line 2310' From S. Line.	
14. PERMIT NO.	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plug and abandon as follows:

Well Depth 1070'

Run 15 sacks of cement from 1070 back to 888.10

Cut Casing at 814.50' from surface

Run Mud from 888.10 back to 142'

Run 100' cement plug 50' in and 50' out of Surface pipe

Run Mud from 42' back to 10'

Run Cement to surface and set marker

Clean debris from site.

19. I hereby certify that the foregoing is true and correct

SIGNED

H. E. Prince

TITLE

owner

DATE

3-20-75

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

APPROVED
MAR 25 1975
H. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side