

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	✓

NEW MEXICO OIL CONSERVATION COMMISSION

OCT 15 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator H. E. PRINCE	5. State Oil & Gas Lease No.
3. Address of Operator 606 N. ATKINSON, ROSWELL, NEW MEXICO 88201	7. Unit Agreement Name
4. Location of Well UNIT LETTER B 990 " FEET FROM THE N LINE AND 2333.22 FEET FROM THE E LINE, SECTION 33 TOWNSHIP 6S RANGE 26E NMPM.	8. Farm or Lease Name OSAGE
	9. Well No. 1
	10. Field and Pool, or Wildcat LINDA SAN ANDRES
15. Elevation (Show whether DF, RT, GR, etc.) 3714 GR	12. County CHAVES

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON AS FOLLOWS:
WELL DEPTH 1070 ft.
RUN 15 SACKS OF CEMENT FROM 1070' BACK TO 889.10
CUT CASING AT 671.50' FROM SURFACE
RUN MUD FROM 889.10' BACK TO 175'
RUN 100' CEMENT PLUG FROM 175' BACK TO 75', 50' IN AND 50' OUT OF
SURFACE PIPE
RUN MUD FROM 75' BACK TO 10'
RUN CEMENT FROM 10' BACK TO SURFACE AND SET MARKER
CLEAN DEBRIS FROM SITE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. E. Prince TITLE OWNER DATE 10-10-74

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE OCT 23 1974

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

plugging