

NO. OF COPIES RECEIVED	1
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	✓

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

OCT 15 1974

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator H. E. PRINCE	8. Farm or Lease Name STURGEON
3. Address of Operator 606 N. ATRINCON, ROSWELL, NEW MEXICO 88201	9. Well No. 2
4. Location of Well UNIT LETTER F 2329 FEET FROM THE W LINE AND 2310 FEET FROM THE N LINE, SECTION 33 TOWNSHIP 68 RANGE 26E NMPM.	10. Field and Pool, or Wildcat LINDA SANANDRES
15. Elevation (Show whether DF, RT, GR, etc.)	12. County CHAVES

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON AS FOLLOWS:

WELL DEPTH 1070ft.

RUN 15 SACKS OF CEMENT FROM 1070' BACK TO 889.10'

CUT CASING AT 671.50' FROM SURFACE

RUN MUD FROM 889.10' BACK TO 157'

RUN 100' CEMENT PLUG FROM 157' back to 57'

50' in and 50' out of surface pipe

RUN MUD FROM 57' BACK TO 10', RUN CEMENT FROM 10' back to surface and set marker.

Clean Debris from site

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. E. Prince TITLE OWNER DATE 10-15-74

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE OCT 23 1974

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging