0 18970	1104	
73456 299707773	$\checkmark$	
(N)	•	
// * M & /		
Submit 3 Copies To Appropriate District Office  State of New Mexico	Form C-103	
District I String Strinerals and Natural Resources	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 8 240	WELL API NO.	
811 South First, Artesia, NM 87210 CONSERVATION DIVISION	30-005-/007/	
107	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Postrict IV Santa Fe, NM 87505	STATE FEE	
District III  1000 Rio Brazos Rd., Aztec, NM 87410  District IV  1220 South St. Francis Dr.  1220 South St. Francis Dr.	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)  1. Type of Well:	Sturgeon	
Oil Well K Gas Well Other		
2. Name of Operator	8. Well No.	
MEW Entrapaire	002	
3. Address of Operator 200 S Kentucky Roswell 88201	9. Pool name or Wildcat	
300 S Kentucky Koswell 88201	Linda San Andres	
4. Well Location		
Unit Letter F: 23/0 feet from the North line and 2	329 feet from the west line	
One Letter not non die nit die	,	
Section 33 Township 65 Range 26E	NMPM Chaus County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.		
3607		
11. Check Appropriate Box to Indicate Nature of Notice,		
	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WOR	K ALTERING CASING	
TEMPORARILY ABANDON	LLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING  MULTIPLE  CASING TEST A	ND 🔲	
COMPLETION CEMENT JOB		
OTHER: OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and g	rive pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac	h wellbore diagram of proposed completion	
or recompilation.	X. a Diena cond Acres	
or recompilation.  Asing person to 1000, Displace hole of 1/2 100 of 5000 ciec. cont to some face. Sill 4/2 of a	egg. Doing said 40-05	
Soul spor pers to 1000 Displace hole up	Gelled Baine, Peat @ 150	
To in 150ss pers at 1000, Disposer holy who	mt. Install day hal	
1/2 1070 my sours ciec. cont to somether, sill the my o	and the same of th	
raf. 1004-40 maken.		
I hereby certify that the information above is true and complete to the best of my knowled	ge and helief	
I hereby certify that the information good in the arm complete to the cost of my		
SIGNATURE Kund White TITLE OWATE		
	DATE <u>01-26-02</u>	
	DATE 01-26-02	
Type or print name Pussel/ Whited		
(This space for State use)	DATE <u>0/-26-02</u> Telephone No.623-2065	
	DATE <u>0/-26-02</u> Telephone No.623-2065	

Plug according to attached procedure -Work must be completed by 2/22/02

Operator Well Unit API #	MEW ENTERPRISE  STURGER #21  F Section 33 Twnship  30-005 - 10071	<u> </u>	TOPS	- -
	+ 60' Surface Plug.		San Andres 518	- - - - -
85/8 "csq	← 157: TAG Shoe Plug			• • • • • • • • • • • • • •
11 Toc 831. 12"csq. 14/2"csq 1070" 150sx cement.	+904', TAG feils 1004'-40',	* Salt gel mud co of gel per barre plug.  * Install dry hole i  * Plugs are to be  * Plugs must not of cement, whic specifically indic  * Shoe and stub p shoe or stub and  * Surface plug wil  * Where plugs are placed inside an in the correct for cement exists.	olugs will be 50' above and below d tagged.	

·