

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN 7-
(Other later)
veter 104)

5. LEASE INFORMATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. OTHER COMMENTS
2. NAME OF OPERATOR Sun Oil Company	8. NAME OF WELL
3. ADDRESS OF OPERATOR P. O. Box 2742, Oklahoma City, Oklahoma	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 460' from East line and 30' from South line of Sec. 20	10. NAME AND POST OFFICE OF TOWNSHIP
14. PERMIT NO.	15. ELEVATIONS (Show whether at, to, or, etc.)
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	17. COPIES OF THIS FORM

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON
CHANGE PLANE

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

SHUTTING WELL
SHUTTING TAPING
ABANDONMENT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and record pertinent to this work.)

Well completed at 5845 p.m. on 5-3-64. On 5-32-64, re-completed at 350'. Completed 4/10 and 1/10/64, for completion of tests at 350'. Also re-completed at 350' and 300'. Completed at 350'. Tested 8 5/8" OD casing, 9400'. 10 minutes, OK.

RECEIVED

JUN 5 - 1964

O. C. G.
ARTESIA, OFFICE

RECEIVED
JUN 4 1964
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(Leave space for Federal or State office use)

TITLE

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

R. L. BEECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100