

Drawer 1857
Roswell, New Mexico 88201

copy to J.F.

November 7, 1967

Mr. J. J. Travis
P. O. Box 873
Midland, Texas

Dear Mr. Travis:

Attached is one approved copy of the Notice of Intention to Abandon your well No. 1 Grant Keyes in the SW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 20, T. 6 S., R. 26 E., N.M.P.M., Federal lease New Mexico 022685. The approval is subject to the condition that the well marker is cemented in the top of the 4 $\frac{1}{2}$ " casing and not "within about 10 feet" of the well. The marker should be a piece of pipe 3" in diameter approximately 10 feet long of which 6 feet is cemented in the 4 $\frac{1}{2}$ " casing with the remaining 4 feet above ground. The well number and location should also be put on the marker.

Sincerely yours,

James W. Sutherland
JAMES W. SUTHERLAND
District Engineer

cc:

~~Roswell (2)~~

NMOCC Artesia

DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Budget Bureau No. 42-R1424

NMOC - ARTESIA

NMOC - HOBBS

BLM - SANTA FE

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

N.M. 022685
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Grant Keyes

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Linda-San Andres

11. SEC. T. R. M. OR B.L. AND SURVEY OR AREA

SW/4 Sec. 20

T-6-S, R-26-E

12. COUNTY OR PARISH 13. STATE

Chaves New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Never Commercial

2. NAME OF OPERATOR

J. J. Travis

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

330 feet from South Line & 330 feet from West Line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3771 Derrick Floor

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

J.J. Travis #1 Grand Keyes Federal was originally drilled to total depth of 1025 feet. The 10 3/4 inch surface casing was set to 300 feet and cemented with 150 sacks; 4 1/2" casing was set to total depth at 1025 feet and cemented with 200 sacks. Casing was perforated from 994 to 1006 feet with two shots per foot and acidized with 4500 gallons of mud acid. Well completed 11-10-64 but was never commercial. Request permission to abandon with following procedure: Place cement plug in bottom of hole across perforations from approximately 950 feet to 1025 feet, fill hole with mud and place cement plug at top of hole in and between 10 3/4 inch and 4 1/2 inch casing if possible, plug to be from surface down to approximate 100 feet from surface. Well marker to be placed in cement in 4 1/2 inch casing if possible, if not well marker to be cemented in ground within about 10 feet of well location. All pipe to be left in hole with exception of 2 inch tubing.

RECEIVED

NOV 6 1967

18. I hereby certify that the foregoing is true and correct

SIGNED

J. J. Travis

TITLE

Operator

DATE 11-3-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

TITLE

RECEIVED

NOV 6 1967

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
BOSWELL, NEW MEXICO

NOV 7 1967

J. W. SUTHERLAND
DISTRICT ENGINEER