

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OLD CONS. COMMISSION
Drawer DD
Artesia, NM 88210

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

August 31, 1985
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM 022584

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLM, AND

SURVEY OR AREA

Sec. 29, T-7-S, R-26-E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

DEC 27 1984

O. C. D.

ARTESIA, OFFICE

Stevens Operating Corporation

P. O. Box 2203 Roswell, New Mexico 88201

14. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990 FSL, 330 FEL, Sec. 29, T-7-S, R-26-E

14. PERMIT NO.

15. ELEVATIONS (Show whether BP, RT, OR, etc.)

3665.7 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and names perti-
nent to this work.)

9 5/8 surface csg @ 103' cement circ. 4 1/2 Production csg @ 1147'.
Approximate TOC 800'.

P & A Proposal:

1. Set CIBP @ 1110' + 35' cement cap.
2. Find Free Point of 4 1/2 casing.
3. Perforate 4 1/2 csg @ 650'. Pump to circ cement to surface outside
4 1/2 csg & will leave cement inside 4 1/2 csg to surface.
4. Set dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Controller

DATE 12-13-84

(This space for Federal or State office use)

APPROVED BY

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

(Orig. Sgd.) PETER W. CHESTER

DEC 26 1984

*See Instructions on Reverse Side