

N. M. O. C. C. COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI  
(Other instructions on reverse side)

Copy to SF

Form approved.  
Budget Bureau No. 42-N1424.

5. LEASE DESIGNATION AND SERIAL NO.  
LC-067811A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dale Federal

9. WELL NO.

1 A

10. FIELD AND POOL, OR WILDCAT

Jessie Springs  
Linda San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

S 27, T 7 S, R 26 E

12. COUNTY OR PARISH  
Chaves

13. STATE  
N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoirs. Use "APPLICATION FOR PERMIT" for such proposals.)

**RECEIVED**

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

AUG 18 1976

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR  
H. F. Prince

O. C. C.  
ARTESIA OFFICE  
88201

P. O. Box 129, Roswell, New Mexico,

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface

1650' from the ~~South~~ line and 330' from the ~~West~~ line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

### 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

#### SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\* ☒

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plug and abandon as follows:

Well depth 1310

Run bottom plug with 15 sacks of cement from 1310' back to 1189.55'

Run heavy mud from 1189.55 back to 155'

Run 100' plug from 155' back to 55'

Run mud for 55' back to 10'

Run 10 feet cement plug and set marker.

Clean debris from site.

**RECEIVED**

AUG 16 1976

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*H. F. Prince*

TITLE

Owner

DATE

8/10/76

(This space for Federal or State office use)

APPROVED

TITLE

DATE

FOR APPROVAL, IF ANY:

**APPROVED**  
AUG 10 1976  
*[Signature]*  
H. L. BEEKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side