

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 15 1974

O. C. C.
ARTESIA. OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator H. E. Prince	8. Farm or Lease Name Sturgeon "A"
3. Address of Operator 606 N. Atkinson, Roswell, New Mexico, 88201	9. Well No. 1
4. Location of Well UNIT LETTER H 1666.5 FEET FROM THE N LINE AND 330 FEET FROM THE E LINE, SECTION 5 TOWNSHIP 7S RANGE 26E NMPM.	10. Field and Pool, or Wildcat Linda San Andrs
15. Elevation (Show whether DF, RT, GR, etc.) 3594.10 G R	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug well and abandon as follows:
Well depth 1031 ft.
* Run 25 sacks of cement from 1031' back to 850.10
Run mud from 850.10' back to 100'
Run cement in and out of casing back to surface and set marker
Clean debris from site.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **H. E. Prince** TITLE **Owner** DATE **10-10-74**

APPROVED BY **W. A. Sussett** TITLE **OIL AND GAS INSPECTOR** DATE **OCT 23 1974**
CONDITIONS OF APPROVAL, IF ANY: *** as noted** Notify N.M.O.C.C. in sufficient time to witness **plugging**