

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

RECEIVED

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>ARTESIA, OFFIC</u>	7. Unit Agreement Name
2. Name of Operator <u>Sam G. Dunn Oil Operations</u>	8. Farm or Lease Name <u>Tonkin</u>
3. Address of Operator <u>P. O. Box 3095 - Lubbock, Texas 79410</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>7S</u> RANGE <u>26E</u> NMPM.	10. Field and Pool, or Wildcat <u>Linda San Andres</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3595 GR</u>	12. County <u>Chaves</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Temporary plugged and abandon</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-3-69

Pull rods and tubing, remove surface equipments.  
Casing left in the hole with cap screwed on the top of casing for protection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm T. Thomas TITLE Geologist DATE 7-23-69

APPROVED BY W. A. Grissett TITLE Oil & Gas Inspector DATE AUG 5 - 1969

CONDITIONS OF APPROVAL, IF ANY: