

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions on
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-067811-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dale Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Leslie Springs
Linda San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S 26-T7S-R26E

12. COUNTY OR PARISH 13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

AUG 18 1976

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

H. E. Prince

O. G. C.

3. ADDRESS OF OPERATOR

P. O. Box 129, Roswell, New Mexico, 88201

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2310 Feet from the S. Line and 2310 feet from the
W. line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plug and abandon as follows:

T. D. 1474

Run bottom plug with 15 sacks of cement from 1474 feet back to 1293.10 feet.

Run heavy mud from 1293.10 feet back to 155 feet.

Run 100 feet cement plug 50 feet in surface pipe 17 sacks and 50 feet in
hole 16 sacks.

Run mud from 55 feet back to 10 feet.

Run 10 feet cement plug and set marker.

Clean debris from site.

RECEIVED

AUG 16 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

H. E. Prince

TITLE

Owner

DATE

8/10/76

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

AUG 17 1976

H. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side