

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.) RECEIVED

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
N. Dale Nichols

3. Address of Operator
P.O. Box 1972 Midland, TX 79702

4. Well Location
Unit Letter P : 660 Feet From The East Line and 660 Feet From The South Line
Section 32 Township 7S Range 27 NMPM Chaves County

7. Lease Name or Unit Agreement Name
Lewis Neff

8. Well No.
3

9. Pool name or Wildcat
Acme (San Andres)

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4020 G.L.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Acidized new and old perforation 1917-1963 with 4000 gal. Halliburton MOD 202 acid.
- 2) Swabbed 50 BBLS. acid with trace oil.
- 3) Pulled tubing and packer. Ran 63 joints tubing and landed seating nipple @ 1956'. Bottom Mud anchor @ 1966'. Ran 2"x10'x1½" pump on 77rods and 8' subs.
- 4) Tested 4 BOPD trace water and gas TSTM
- 5) Return to producing status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE N. Dale Nichols TITLE Operator DATE 7-18-89
TYPE OR PRINT NAME N. Dale Nichols TELEPHONE NO. (915) 682-6521

(This space for State Use)
ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

DATE JUL 21 1989