Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103	
Revised 1-1-89)

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088

P.O. Bo
IRICT II
Drawer DD, Anesia, NM 88210

Santa Fe, New Me.

WELL API NO. 30-005-10472

Santa Fe, New Mexico 87504-2088			
P.O. Drawer DD, Artesia, NM 88210 Salita Fe, New Mexico 87504-2088	5. Indicate Type of Lease		
DISTRICT III	STATE X FEE		
1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.		
CHAIDDY MOTIONS AND DEPOSITS CONVENIES	VA-613		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		
DIFFERENT RESERVOIR LISE *APPLICATION FOR DEDUIT*	7. Lease Name of Unit Agreement Name		
(FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well:	Avalanche-Journal-State		
1. Type of Well: Oil. WELL X WELL OTHER 2. Name of Operator	Avalanche-Journal-State		
1007	Well No.		
N. Dale Nichols & SEP 1997	<u> </u>		
3. Address of Operator P. O. Poy, 1072, Middland, TV 70702	Pool name or Wildcat		
P.O. Box 1972 Midland, TX 79702 RECEIVES	Acme San Anders		
1	220		
Unit Letter 1 : 2310 Feet From The South Line and	Feet From The West Line		
Section 4 Township 8-S Range 27 E			
Township 0-3 Range 2/ E NMPM Unaves County 10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
<i>(////////////////////////////////////</i>			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
MOTION OF COMMENTS	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K X ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	LLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING CASING TEST AN	ND CEMENT JOB		
OTHER: OTHER:			
13 Page 1			

- 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- Riged up Pulling Unit.
- 2) Pulled tubing. Recovered 11 joints.
- 3) Ran impression block. 2" pipe looking up.
- 4) Ran 3 5/8 over shot. Cought fish. Taged up. Straped out hole top fill 1943. PBTD 1946. Perfs 1916-40. Layed out all Tubing.
- 5) Ran 60 joints new tubing (1893'). Seating nipple & perforted mud ancher.
- 6) Ran 10x2" traceling bbl pump on tapered string 3/4 & 3/8" rods.
- 7) Pumped 2.05 BO no water in 24 hrs. after recovering 30 bbls flush production.

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM	SEP 2 6 1997
TYPE OR PRINT NAME N. Dale Nichols	TELEPHONE NO. (915)682-56
\sim 1.1 \sim 1.1	Owner
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	