

NO. OF COPIES RECEIVED	8
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	2
LAND OFFICE	1
OPERATOR	3

# NEW MEXICO OIL CONSERVATION COMMISSION

30-005-10429  
Form C-101  
Revised 1-1-65

5A. Indicate Type of Lease	STATE <input type="checkbox"/>	FEE <input type="checkbox"/>
5. State Bill	3634	Lease No.

## APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work		7. Unit Agreement Name	
b. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		8. STANDARD STATE	
2. Name of Operator DR. SAM G. DUNN		9. Well No. 6	
3. Address of Operator POST OFFICE BOX 192 ARTESIA, NEW MEXICO		10. ACME SAN ANDRES	
4. Location of Well UNIT LETTER G LOCATED 1980 NORTH 2310 EAST 5 FEET FROM THE LINE AND FEET FROM THE LINE OF SEC. TWP. RGE. NMPM		12. CHAVES	
21. Elevations (Show whether DF, RT, etc.)		19. Proposed Depth 2000	
21A. Kind of Status Plug. Bond BLANKET		19A. ACME SAN ANDRES ROTARY	
21B. Drilling Contractor		22. Approximate Date will start 8-11-66	

## PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
11"	8 5/8"	26#	150	150	
8"	4 1/2"	9 1/2#	2000	200	

CEMENT CIRCULATED 150' OF 8 5/8" CASING THEN DRILLED TO 2000' THROUGH ACME SAN ANDRES SECTION. CIRCULATED CEMENT WITH 250 SACKS. THEN LOG PERFORATED THROUGH 4 1/2" AND COMPLETE WITH ACID.

APPROVAL VALID  
FOR 90 DAYS UNLESS  
DRILLING COMMENCED,  
EXPIRES 11-7-66

RECEIVED

AUG 10 1966

O. C. C.  
ARTESIA, OFFICE

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed William Hall Title AGENT Date 8-9-66

(This space for State Use)

APPROVED BY M. L. Armstrong TITLE OIL AND GAS INSPECTOR DATE AUG 10 1966

CONDITIONS OF APPROVAL, IF ANY:

# Memo

From  
W. A. GRESSETT  
DEPUTY OIL & GAS  
INSPECTOR

To

Unable to drill below  
170' due to being in the  
Railroad mtn. fault.

to Plug & more 330' south.  
as per phone conversation  
with Mr. McEldon