	<u> </u>			Form C-103
DISTRIBUTION		ne	0514	Supersedes Old
SANTA FE	/	NEW MEXICO OIL CON	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
TILE	/-			
J.S.G.S.		.1	AN 1 4 then	5a. Indicate Type of Lease
AND OFFICE			(§ 1 M)	State Fee
PERATOR	3		A STATE OF THE STA	5. State Oil & Gas Lease No.
		677		
(DO NOT USE THIS F	SUNDE	LY NOTICES AND REPORTS ON	1 WELLS	
US	E "APPLICAT	POSALS TO DRILL OR TO DEEPEN OR PLUG ION FOR PERMIT -** (FORM C-101) FOR SU	CH PROPOSALS.)	
OIL GAS		OTHER- Test Well		7. Unit Agreement Name
Name of Operator	LL []	OTHER-		8. Farm or Lease Name
Citie	s Servi	ce Oil Company		
Address of Operator				9. Well No.
P. 0.	. Box 6) - Hobbs, New Mexico &	18240	1
Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER	· · · · · ·	1980 FEET FROM THE South	1980	Wildcat Vildcat
	- ,	TOTAL TROOP THE	LINE AND FEET	FROM
THE East	LINE, SECTION	78 TOWNSHIP	28g	
			NARYSN	MPM
		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	777777	Est. 40	00 G. L.	Chaves
•	Check	Appropriate Box To Indicate 1	Nature of Notice, Report of	
NOT	ICE OF IN	TENTION TO:		ENT REPORT OF:
_	_			
ERFORM REMEDIAL WORK	-			A : ========
ENTORM REMEDIAL WORK	=	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON		PLUG AND ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMEN
EMPORARILY ABANDON		CHANGE PLANS		
EMPORARILY ABANDON ULL OR ALTER CASING			COMMENCE DRILLING OPNS.	
EMPORARILY ABANDON ULL OR ALTER CASING OTHER	ompleted Op		COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER	PLUG AND ABANDONMEN
other Describe Proposed or C work) SEE RULE 1103. Drilled to a T. Set 2716' of 4. 11:25 PM 11-30. Tested P-4 zon. w/5000 gal. Uni holes. Acidize sealers. No si	.0. of : 1 00, 966. W 2594-: 1 sol and ad w/300 how. To	CHANGE PLANS	commence drilling opns. CASING TEST AND CEMENT JOB ATTEMN TO 3070 to 125'. Cemented w/300 100# for 30 minutes w/30 gainow. Tested P-3 zone 11 zed w/5000 gain. Units 172-2413 through seven	plug and abandonmen adding estimated date of starting any property 2970 to cover Glorieta sax Incor. Plug down a no drop in pressure. mud/acid. Reacidized 2486-2501 through six and six ball holes. Acidized w/350
emporarily abandon unter casing other Describe Proposed or C work) SEE RULE 1103. Drilled to a T. Set 2716' of 4: 11:25 PM 11-30- Tested P-4 zone w/5000 gal. United to a Company to the company t	. 0. of 3 20, 966. When 2594-3 1 sol and sol w/300 how. To 1 and sol w/300 how. To 1 and sol pon.	erations (Clearly state all pertinent det 3070. Displaced 30 sectors, 5# J-55 (84 jts.) et 27 38 24 hrs. Tested to 10 8623 ghrough seven holes 15 ball sealers. No sh 2 gal. mud/acid. Reacid 2 sted Pl and P2 zones 23 3 seven ball sealers. Test	commence drilling opns. CASING TEST AND CEMENT JOB OTHER Dails, and give pertinent dates, including the second with the sec	plug and abandonmen adding estimated date of starting any property 2970 to cover Glorieta sax Incor. Plug down a no drop in pressure. mud/acid. Reacidized 2486-2501 through six and six ball holes. Acidized w/350

CONDITIONS OF APPROVAL, IF ANY:

. The first of the first of the second of th

and the second of the second o

ing the state of t