

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Test Well</b>		7. Unit Agreement Name
2. Name of Operator <b>Cities Service Oil Company</b>		8. Farm or Lease Name <b>O'Brien "E"</b>
3. Address of Operator <b>P. O. Box 69 - Hobbs, New Mexico 88240</b>		9. Well No. <b>#1</b>
4. Location of Well UNIT LETTER <b>1-I</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>34</b> TOWNSHIP <b>8s</b> RANGE <b>29E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3996 D.F.</b>		12. County <b>Chaves</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**This well was drilled to a total depth of 3730' with 'no show'.**

**We now propose to plug and abandon in the following manner:**

1. Load hole with mud laden fluid.
2. Displace 60 sacks from 3730-3530.
3. Displace 30 sacks plug across top of San Andres 2418-2318.
4. Displace 30 sacks plug  $\frac{1}{2}$  in and  $\frac{1}{2}$  out of 8 5/8 surface casing 515-415.
5. Put 10 sack plug in top of 8 5/8 from bottom of cellar to 30' and install 4" pipe marker.
6. Clean location of all equipment and debris, fill pits and cellar.

RECEIVED

FEB 22 1967

N. M. O. C.  
N. M. O. C. OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Gressett TITLE District Clerk DATE February 21, 1967

APPROVED BY W. A. Gressett TITLE Oil and Gas Inspector DATE FEB 22 1967

CONDITIONS OF APPROVAL, IF ANY:

[illegible]