

RECEIVED

MAR 29 1967

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	7
FILE	7
J.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Orig & 2cc: OCC, Artesia
cc: Regional Office
cc: Partners
cc: file

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Sinclair Oil & Gas Company	8. Farm or Lease Name J. G. O'BRIEN
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well D 660 FEET FROM THE North LINE AND 660 FEET FROM West LINE, SECTION 1 TOWNSHIP 9S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether, DF, RT, GR, etc.)	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Perforate, treat and test <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-19-67 Jet perforated San Andres 3114-17' and 3123-27' w/14-3/8" holes. M. A. washed to San Andres perms. 3114-27' w/500 Gal. M.A. Max. Press. 2700#, Min. 1800# @ 1 BPM
- 3-23-67 ISIP 2200#, 10 mins. SIP 1000#. O# in 25 mins. Swabbed San Andres perms. 3114-17' and 3123-27' 56 BFW plus 1 Bbl. dead oil in 5 hours. Swabbed from 3000' w/500' FIH.
- 3-24-67 Spot 50 sks. Class C cement 2850-3350', filled hole w/heavy mud. Cut 4-1/2" OD casing @ 2173' and pulled. Spotted 25 sacks cement plug top of 4-1/2" OD casing stub from 2123-2223'. Spot cement plug 50 sacks 600' to 700', 50 sacks 250' to 350' bottom of 8-5/8" OD casing and 10 sacks in top of 8-5/8" OD casing @ surface. Installed regulation dry hole marker, cleaned and levelled location. Plug and Abandoned off: 3-25-67.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 3-27-67APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: