``	-191
Submit 3 Copies To Appropriate District 23456, 29 State of New Mexico	Form C-103
District Facing Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88340 District II	WELL API NO. 30-005-60020
District II 1301 W. Grand Ave., Artesia, N. 88210 District III 1000 Rio Brazos Rd., Aztec, N. 627410 District III 1000 Rio Brazos Rd., Aztec, N. 627410 ARTES Sorte Fo. N. 627505	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM \$7410 District IV Santa Fe, NM 87505	STATE X FEE
1220 S. St. Francis Dr., Santa Fe, WA	6. State Oil & Gas Lease No. 7546
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	Diablo State
Oil Well (Gas Well Other 2. Name of Operator	8. Well No.
Slayton Resources, Inc.	2
3. Address of Operator P.O. Box 2035, Roswell, NM 88202-2035	Pool name or Wildcat Diablo San Andres
4 Well Location	Diable ban Andres
Unit Letter I 1980 feet from the S line and	600feet from the _ Eline
Costion Township to a Pongo 077	NMPM at County
Section 16 Township 10S Range 27E 10. Elevation (Show whether DR, RKB, RT, GR, or state of the	NMPM Chaves County
11. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO: , SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON A REMEDIAL WO	ORK ALTERING CASING
TEMPORARILY ABANDON	RILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST COMPLETION CEMENT JOB	AND
OTHER: OTHER:	
Describe proposed or completed operations. (Clearly state all pertinent details, and starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach	give pertinent dates, including estimated date of wellbore diagram of proposed completion or
recompilation.	
recompilation. We intend to MI RU. Tag TD @ 2070'.	
·	<u>.</u> 9
We intend to MI RU. Tag TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement.	
We intend to MI RU. Tag TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement.	
We intend to MI RU. Tag TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement.	
We intend to MI RU. Tag TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — Tag Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350', Pump 35 sks of class c cement. Set dry hold marker and level location.	100'plug inside ; outside of 5/2 255. 250-350' lug-inside ; outside 5'2'csq.
We intend to MI RU. Tag TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — Tag Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350', Pump 35 sks of class c cement. Set dry hold marker and level location.	
We intend to MI RU. Tag TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — Tag Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350', Pump 35 sks of class c cement. Set dry hold marker and level location.	100'plug inside ; outside of 5/2 255. 250-350' lug-inside ; outside 5'2'csq.
We intend to MI RU. 'Tag 'TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — Tag Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350', Pump 35 sks of class c cement. Set dry hold marker and level location. 60' P	100'plug inside = outside of 5/2 255. 250-350' lug-inside = outside 5'2'csq.
We intend to MI RU. 'Tag 'TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — Tag Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350', Pump 35 sks of class c cement. Ming Set dry hold marker and level location. 60' p Notify OCD 24 hrs. prior to any work done	100'plug inside \$0utside of 5/2 255. 250-350' lug-inside \$ Outside 5'k'csq. 60'
We intend to MI RU. 'Tag 'TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — 74 Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350'. Pump 35 sks of class c cement. Min. Set dry hold marker and level location. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge.	100'plug inside \$0utside of 5/2 255. 250-350' lug-inside \$ Outside 5'k'csq. 60'
We intend to MI RU. Tag 'TD @ 2070'. Set 1st plug @ 2070'. Pump 35 sks of class c cement. — Tag Set 2nd plug @ 1490'. Pump 35 sks of class c cement. Set 3rd plug @ 350'. Pump 35 sks of class c cement. Set dry hold marker and level location. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledges. SIGNATURE SIGNATURE SIGNATURE TITLE AGEN TITLE	100'plug inside = outside of 5/2 255. 250-350' lug-inside = outside 5'2'csq.