Submit 3 Copies to Appropriate District Office

State of New Mexico als and Natural Resources Department Energy, M

Form	C	·10	3
Revise	d	1.1	4

DISTRICT I P.O. Box 1980, Hobbs, NM 88:	OIL CONSER	O. Box 2088	WELL API NO.			
DISTRICT II P.O. Drawer DD, Artesia, NM	Santa Fe, Nev	w Mexico 87504-2088	5. Indicate Type of Lease STATE XX FEE			
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. E-8879			
	NOTICE AND DEPORT	EVINTWIPHES NATIONAL				
(DO NOT USE THIS FORM DIFFERE	RY NOTICES AND REPORT FOR PROPOSALS TO DRILL OF NT RESERVOIR. USE "APPLICATI (FORM C-101) FOR SUCH PROPO	7. Lease Name or Unit Agreement Name				
1. Type of Well: OIL WELL XX	GAS WELL OTHER	APR 0 8 1997	McAlester State			
2. Name of Operator		ML COM, DIV.	8. Well No.			
Mountain Stat	es Petroleum Corporat	ion William	8			
3. Address of Operator			9. Pool name or Wildcat			
PO Box 1936	Roswell, NM 88202		Coyote Queen			
4. Well Location						
Unit LetterF	: 2310 Feet From The	North Line and 23	10 Feet From The West Line			
10	Township 11S	Range 27E	NMPM Chaves County			
Section	Township LLS	Show whether DF, RKB, RT, GR, etc.)				
<i>\////////////////////////////////////</i>	(//////////////////////////////////////	695 GR				
<i>\////////////////////////////////////</i>			enort or Other Data			
		Indicate Nature of Notice, R	cport, or Other Data			
NOTICE	OF INTENTION TO:	SUE	SSEQUENT REPORT OF:			
		ON XX REMEDIAL WORK	ALTERING CASING			
FERFORM REMEDIAL WORK						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN						
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB					
OTHER:		OTHER:				
			Il and the state of the state o			
12. Describe Proposed or Comp	leted Operations (Clearly state all perti-	nent details, and give pertinent dates, incli	ding estimated date of starting any proposed			
work) SEE RULE 1103.						
			•			
Веса	ause of the shallow d	epth of this well, cop	y of ClO5 enclosed,			
we n	Because of the shallow depth of this well, copy of ClO5 enclosed, we propose to; Run TBG $\tau 0$ $\tau \rho$ χ					
Pull rods, pump and tubing as necessary, fill casing from TD to						
surface with cement and run the sand line-sinker har several						
+ im	es while comenting to	eliminate any air poc	kets .			
CIM	cp willie compilering or	, ,				
Set dry hole marker and clean location of any equipment, pipe,						
	tanks and junk.					
Lan	ks and Junk.					
	1 Maria Maria	throwledge and helief				
I hereby certify that the information above is true and complete to the feet of my knowledge and belief.						
SIGNATURE SALL	& Secullow	TILE	DATE04/04/97			
UNITATION -	' //		mary word NALITY LVA			
TYPE OR PRINT NAME	V		TELEPHONE NO.			
(This space for State Use)	name o receive the control of the co	- 23 - 4d -	ADD 0.1 4009			
900	was to demand at the a	a same xin pro-	APR 2.1 1997			

DISTRICT A SUPERVISOR