

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1967

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Union Oil Company of California		8. Farm or Lease Name Kitchens
3. Address of Operator P. O. Box 671, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 9-S RANGE 26-E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3705.5 GR		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Reached total depth at 5755' on 11-30-67. Well failed to produce. Received verbal permission 12-1-67 from Mr. W. A. Gressett to plug and abandon.

Plug #1 - 5550' to 5433' - 35 sack cement plug.

Plug #2 - 4050' to 3933' - 35 sack cement plug.

Plug #3 - 1250' to 1133' - 35 sack cement plug.

Plug #4 - 35' to surface.

Laid down drill pipe and cut off well head. Welded vented plate on 8-5/8" casing and installed dry hole marker. Plugging completed 12-3-67.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. G. Ladd, Jr. R.G.Ladd, Jr. TITLE District Drilling Supt. DATE 12-5-67

APPROVED BY [Signature] DATE 12-5-67

CONDITIONS OF APPROVAL, IF ANY: