

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYN. M. O. C. C. COPY  
SUBMIT IN TRI-CATE®  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 044040

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

U.S. Phillips

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SUBSET OR AREA

Sec. 22, T-11S, R-26E

12. COUNTY OR PARISH

Chaves

13. STATE

N. Mex.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Delaware-Apache Corporation

3. ADDRESS OF OPERATOR

1720 Wilco Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.  
At surface660' FEL & 1980' FSL, Sec. 22, T-11 S, R-26 E, Chaves  
County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3657.9 GR.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Delaware-Apache Corporation notified Mr. Knauff, Artesia, New Mexico, 3-20-69 of intention to plug and abandon well.

Halliburton Set cement plugs at 1450-1550 with 30 sacks cement.

2065-2165 with 30 sacks	Set 20 sacks in top of 8 5/8" csg.
3510-3610 with 30 sacks	Installed Dry Hole Marker.
4260-4360 with 30 sacks	Rig Released 7:00 am 3-21-69
5070-5170 with 30 sacks	
5840-5940 with 30 sacks	

Well was plugged and abandoned 3-20-69.

Formation tops:	San Andres	830'
	Glorieta	2115'
	Tubb	3540'
	Abo	4310'
	Wolfcamp	5120'
	Sil. Devonian	5890'
	Gr. Wash	6010'

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE Production Secretary

DATE 3-21-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side