	17	 -					Form C-103	
NO. OF COPIES RECEIVED	DF COPIES RECEIVED						Supersedes Old	
DISTRIBUTION			EW MEXICO OIL	C-102 and C-1 Effective 1-1-6				
SANTA FE		NE	IM WEXICO OIL	CONSE			Elicetive 14	
FILE	1				FEB 1 0 1970	{	5a. Indicate Type	of Lease
U.S.G.S.	1			State	Fee, 🛣			
LAND OFFICE	+				G. C. S.		5. State Oil & Gas	s Lease No.
OPERATOR	11			,	ARTESIA, CARICE			
		UDDIV NOTICES	AND DEBORT				HHIIII	THITTINI THE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)								
USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPUSALS.)							7. Unit Agreemen	Name
OIL GAS	. \square	OTHER-						
2. Name of Operator							8, Farm or Lease Name	
Strat-Trap Petroleum, Inc.							Midwest-O'Brien	
3. Address of Operator							9. Well No.	
203 V&J Tower Bldg., Midland, Texas 79701							1 1	
4. Location of Well							10. Field and Pool, or Wildcat	
							Wildcat	
UNIT LETTER I . 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM							THITTE	
Foot		SECTION 28	٠٤	35	PANGE 28E	NMPM.		
THE <u>East</u>	LINE, S	SECTION	TOWNSHIP		RANGE	NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)							12. County	
4015 GL							Chaves	
16.	777			nata N	ature of Notice, Re	port or Oth	er Data	
				ate IV	ature of Hottee, Re	BSECHENT	REPORT OF:	
NOTI	CEO	F INTENTION	10:		30	BSEQUENT	1121 0111 011	
г	_		PLUG AND ABANDO	┌┐│	REMEDIAL WORK	<u> </u>	ALTER	ING CASING
PERFORM REMEDIAL WORK	╡		PLUG AND ABANDU	" ''		. 片		IND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.								
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB COMP							etion	
					VIII.N			
OTHER								
17. Describe Proposed or C	omplet	ted Operations (Clea	irly state all pertin	ent deta	ils, and give pertinent da	tes, including	estimated date of	starting any proposed
work) SEE RULE 1103.								
12-9-69 Rigge	d up	Pulling Uni	it. Pulled	rods	and pump.			
12-11-69 Repai:	red	pump. Ran r	oump, tubing	g and	rods. Put bac	k on pump	•	
12-14-69 Pulle	d pu	ump. rods and	d tubing.					
12-15-69 Ran R4 tension packer on tubing. Set packer at 2572'. Swab upper zone.								
12-16-69 Ran rods & put back on pump.								
		_						
								
18. I hereby certify that the	infor	mation above is true	and complete to the	he best	of my knowledge and belie	ef.		
\mathcal{N}_{i}	,	*				•		
TITLE President DATE 2-6-70								6-70

OIL AND GAS INSPECTOR

MAR 2 1970