

N. M. O. C. C. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0279164 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rita "A" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 24, T-14-S, R-28-E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Dry Hole**

2. NAME OF OPERATOR

Kingery Drilling Co., Inc.

3. ADDRESS OF OPERATOR

Box 1588, Ardmore, Oklahoma 73401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FS & WL, Section 24, T-14-S, R-28-E,
18 miles East of Hagerman

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3638 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-13-70 Rig up and run Gamma Tie-in log. Perforate 2 1/2" J.P.F. 1392' to 1398' 12 Holes
Run 44 Joints 2-3/8" EUE 8rd Thd Tubing and 2-3/8 x 5 1/2" Baker Model "R" double
grip packer
Set tubing at 1365.39', - Packer at 1304'
Swab well dry. Acidize with 500 gals. MCA. 15% Acid. Break down at 1500 PSI
Treats at 1600 PSI @ 1/4 B.P.M. Breaking 1400 PSI @ 2 1/4 B.P.M. ISDP=1100 PSI
5 min. shut in = 600 PSI. Total load 18 bbls. Start swabbing at 9:00 P.M.
Fluid level at 1200' from surface with 14 bbls recovered at 10:00 P. M. All
load recovered at 1:30 A. M. Swabbing from 1300'. 100% Salt water.

5-14-70 Well left open for 6-hours to check fluid entry. Well had 800' of fluid at
7:30 P. M. Checked for oil. - None.
Swabbed approximately 10-bbls. Total recovery 28 bbls. Load + 10 bbls.
Catch sample of water on 1st run.

RECEIVED

JUN 4 1970

O. C. C.

ARTESIA, OFFICE

RECEIVED

JUN- 1970

U. S. GEOLOGICAL SURVEY

ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

May 28, 1970

(This space for Federal or State office use)

DISTRICT ENGINEER

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.