

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

N. M. O. C. C. COPY

NEW MEXICO OIL CONSERVATION COMMISSION

Copy to SF
Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> <u>Federal</u> <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. <u>NM 0279164 A</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <u>Dry Hole</u>	7. Unit Agreement Name
2. Name of Operator <u>Kingery Drilling Co., Inc.</u>	8. Farm or Lease Name <u>Rita "A" Federal</u>
3. Address of Operator <u>Box 1588, Aramore, Oklahoma 73401</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>S.</u> LINE AND <u>1980</u> FEET FROM THE <u>W.</u> LINE, SECTION <u>24</u> TOWNSHIP <u>14S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3638 GR.</u>	12. County <u>Chaves</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Received permission to Plug and Abandon by telephone from Mr. Knuff

Run tubing, fill hole with good mud
Set 25 sacks cement plug 1475' to 1285'
Cut and remove 5 1/2" Casing
Run tubing and set 25 sacks cement plug 400' to 300'
Set 10 sacks cement plug 10' to 0'
Install regulation Marker
Clean location

RECEIVED

JUN 4 1970

O. C. C.
ARTESIA, OFFICE

RECEIVED
JUN - 1 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>President</u>	DATE <u>May 7, 1970</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>DISTRICT</u>	DATE <u>JUN 1 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		