

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

clsr
Opt

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

MAR 20 1992

O. C. D.
ARTESIA OFFICE

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

FEE

7. Lease Name or Unit Agreement Name

VAN-EATON LEYENDECKER

8. Well No.

1

9. Pool name or Wildcat

Undesignated ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

McClellan Oil Corporation

3. Address of Operator

P.O. Drawer 730

Roswell, New Mexico 88202

4. Well Location

Unit Letter L : 1980 Feet From The SOUTH Line and 660 Feet From The WEST Line

Section 22 Township 6-s Range 27-e NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4149' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

85/8" csg. -- 1380'
41/2" csg. --- 6575' 10.5#
23/8" Tbg. ---- EUE

C.I.B.P. = 5150' - 50' cement
T.O.C. = 4200'
Perfs. = 5039' - 5044'

35' PROPOSAL

1. Set C.I.B.P. at 4980'. Dump 30' cmt. on top
2. Run tbg. to 4680' and circulate hole with heavy gel H₂O.
3. 1st. plug 4680' - 4580' 25sx. 10. 60' - surface 100'
4. Shoot off csg. at 4150' and pull. 11. Install dry hole marker
5. 2nd. plug 4200' - 4100' 30sx. Tag
6. 3rd. plug 3980' - 3880' 30sx.
7. 4th. plug 2520' - 2420' 30sx. 2570 - 2470
8. 5th. plug 1430' - 1330' 30sx. (TAG)
9. 6th. plug 1000' - 900' 30sx.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mitch Lee TITLE DRLG. & Completion Eng. DATE 3/19/92

TYPE OR PRINT NAME Mitch Lee

TELEPHONE NO. (505) 622-3200

(This space for State Use)

APPROVED BY [Signature] TITLE Plugging DATE 4/7/92

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.C.C. in sufficient time to witness