Submit 3 Copies To Appropriate District	State of New N	lexico	Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240	bbs, NM 88240		WELL API NO.
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-60144
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	100 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			VO-5081
87505 SUNDRY NOTIC	ES AND REPORTS ON WELI	S	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Bouse Name of Cant rigidement Name.
			South Acme AZM State
1. Type of Well:		=123.	
Oil Well Gas Well X	Other \(\begin{array}{c} 30^{3\text{*}} \end{array}	-123456	
2. Name of Operator	/gV	A 0	7. Well No.
Yates Petroleum Corpor	ation 🞊 💮	State of the state	#1
3. Address of Operator	7.65.20 L	PECEIVED	8. Pool name or Wildcat
105 S. 4 th Street Artesi) ARTESI	Undes. Foor Ranch Pre-Permian
	\ <u>a</u>	THE COL	
4. Well Location			
Unit Letter MA: 66	60 feet from the South	line and 660	feet from the West line
Offit Letter	recention the <u>soom</u>	mic and	rect from the mile
Section 30	Township 8S Range	27E	NMPM Chaves County
	10. Elevation (Show whether	DR, RKB, RT, GR, et	c.)
3997' GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB	
	COMPLETION	OLIVILIA 30B	<u> </u>
OTHER:		OTHER: spud re	· · · · · · · · · · · · · · · · · · ·
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
3/20/02 – MIRU pulling unit.			
3/21/02 – Remove dry hole marker. TIH and tag at 2165'. Wash fill from 2165-2195'. Drill 1' new hole. No			
communication with surface behind 8-5/8" casing.			
3/22/02 – Work 8-5/8" casing to establish circulation behind. Cement with 450 sxs Class C + 2% CaCl2.			
Displaced with brine down to 1275'. Circ 20 sxs. WOC 1 hour. Cement fell back. Top off with 20 sxs.			
Rig down pulling unit and turn	well to drilling departmen	t.	
		•	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
1	-		
SIGNATURE MATTER HE	TITLE _	Engineering Tec	hnician DATE March 27, 2002
Type or print name Susan Hei			Telephone No. 505-748-1471
(This space for State use) ORIGINAL SIGNED BY TIM W. GUM DESTRUCT IN SUPERVISOR			
APPPROVED BY	TITLI		DATHAPR 17 2002
Conditions of approval, if any:			₩ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

...