

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

SEP 28 1973

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Read & Stevens, Inc. ✓ 3. Address of Operator P.O. Box 2126, Roswell, New Mexico 88201 4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>16</u> TOWNSHIP <u>6-S</u> RANGE <u>27-E</u> NMPM.	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. K-4025, L-2463 7. Unit Agreement Name 8. Form or Lease Name New Mexico "L" State 9. Well No. 1 10. Field and Pool, or Wildcat Haystack - Cisco 12. County Chaves
15. Elevation (Show whether DF, RT, GR, etc.) 4097 DF, 4986 GL	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug well as follows:

Cut 4 1/2" casing at approximately 4800' and pull.
 Fill hole with good mud.
 Set cement plug over perfs. 5890-5902'. 25 SX *
 Set 35 sack cement plug at 4 1/2" casing stub.
 Set cement plug 2400-2500'. 35 SX *
 Set cement plug 1370-1470 (base of 8 5/8" casing). 35 SX *
 Set surface plug.
 Install regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carla Shellinger TITLE Agent DATE 9/26/73

APPROVED BY W. A. Gussett TITLE OIL AND GAS INSPECTOR DATE OCT 1 1973

CONDITIONS OF APPROVAL, IF ANY:
* as noted above
Notify N.M.O.C.C. in sufficient time to witness
plugging, starting w/ plug c. 4 1/2" stub