

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION  
JUN 15 1971

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

O. C. C.  
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator American Trading and Production Corporation	8. Farm or Lease Name O'Brien "24"
3. Address of Operator Post Office Drawer 992, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>8-S</u> RANGE <u>28-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3989' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 50 sx. cement plug 2640' - 2490'.  
 Spot 50 sx. cement plug in and out of 4 1/2" casing stub (depths to be determined).  
 Spot 50 sx. cement plug in and out of surface 470' - 320'  
 Spot 10 sx cement plug.  
 Weld steel plate to surface casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>W. P. Gressett</u>	TITLE <u>Production Superintendent</u>	DATE <u>June 11, 1971</u>
APPROVED BY <u>W. P. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>JUN 16 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

**JUN 14 1971**

**OIL CONSERVATION COMM.  
HOBBS, N. M.**