16.

N. M. O. C. C. COPY, UNITED STATES

DEPARTMEN OF THE INTERIOR verse side) instructions

SUBMIT IN TRIPLIC 'TE*

Form approved. Budget Turean No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM-0390104

(Do not use this form for proposals to drill or to deepen or plug to Use "APPLICATION FOR PERMIT—" for such p	back to a different reservoir.	-
1. OIL GAS WELL X OTHER 2. NAME OF OPERATOR	RECEIVED	8. FARM OR LEASE NAME Shenandonh Fed "M"
Read & Stevens, Inc. 3. ADDRESS OF OPERATOR P. O. Box 2126, Roswell, New Mexico 88201 4. LOCATION OF WELL (Report location clearly and in accordance with any See also space 17 below.) At surface 1980' FWL & 1980' FSL Sec. 28, T-6-S, R-27-	O. C. C.	9. WELL NO. 1 10. FIELD AND POOL, OR WILDCAT Haystack-Cisco 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-6-S, R-27-E
(Cl hothown	P PT CR etc.)	12. COUNTY OR PARISH 13. STATE

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. New Mexico Chaves 3944 DF - 3933 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
NOTI		[]	THE CALL OF THE	REPAIRING WELL:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASING	
FRACTURE TREAT	MULTIPLE COMPLETE		SHOOTING OR ACIDIZING	ABANDONMENT*	X
SHOOT OR ACIDIZE	ABANDON*		(01)		
REPAIR WELL	CHANGE PLANS		(Note: Report results of multipl Completion or Recompletion Repo	e completion on Well rt and Log form.)	-
(Other)		<u> </u>	Completion of Recompletion	estimated date of sta	rtin

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged as follows:

Set CIBP @ 5500' with 4 sx. cement on top plug.

Cut 2 7/8" casing @ approx. 4500' & pulled.

Set cement plugs as follows with heavy mud between plugs:

Set 35 sx. cement plug @ 4500'-4400'

Set 35 sx. cement plug @ 2400'-2300'

set 35 sx. cement plug @ 1450'-1350'

Set 10 sx. cement plug @ 10'-

Cut off well head

Installed regulation dry hole marker.

Will notify when location is ready for inspection.

MAR LENVED

ARTESIA, NEW MEXICO

		-	<i></i>
		1.2	
18. I hereby certify that the foregoing is true and correct		- /a m /m/A	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	TITLE Agent	$DATE = \frac{3/15/74}{}$	
SIGNED - AL LEGGEL	TITLE		
	A CONTROL OF THE PARTY OF THE P		
(This space for Federal or State office use)			
· · · · · · · · · · · · · · · · · · ·		DATE	

*See Instructions on Reverse Side