

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL AND GAS CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

OCT 7 1971

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>254259</b>

<b>D.C.C.</b> <b>ARTESIA OFFICE</b> SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" FORM C-101 FOR SUCH PROPOSALS.)</small>		
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name	
2. Name of Operator <b>The Rodman Corporation</b>	8. Farm or Lease Name <b>State</b>	
3. Address of Operator <b>P. O. Box 3826, Odessa, Texas 79760</b>	9. Well No. <b>1</b>	
4. Location of Well UNIT LETTER <b>H</b> <b>1980</b> FEET FROM THE <b>N</b> LINE AND <b>460</b> FEET FROM THE <b>E</b> LINE, SECTION <b>28</b> TOWNSHIP <b>14S</b> RANGE <b>28E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Wildcat</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>3580 GR.</b>	12. County <b>Chaves</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**We propose the following plugging procedures in agreement with Mr. Bill Gressett, State oil and Gas Rep., Artesia, N.M.**

- ID 8781*
- 1 - 30 ex. cmt. plug @ 8625'
  - 2 - 30 ex. cmt. plug @ 8455'
  - 3 - 30 ex. cmt. plug @ 8035'
  - 4 - 30 ex. cmt. plug @ 6560'
  - 5 - 30 ex. cmt. plug @ 5382'
  - 6 - 30 ex. cmt. plug @ 3232'
  - 7 - Shoot 8 5/8" csg @ free point and pull.
  - 8 - 50 ex. cmt. plug in and out of 8 5/8 csg where shot off.
  - 9 - 115 ex. cmt. plug in and out 12 3/4 csg. (shoe) *450' to 300'*
  - 10 - 10 ex. cmt. plug top 12 3/4" csg. with welded dry hole marker in place.
  - 11 - Clean and level location and pits.
- > 405X. CMT Plug @ 2030' to 1935' in 4047-8 5/8*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Jim Payne</i></u>	TITLE <b>Area superintendent</b>	DATE <u><i>10-2-71</i></u>
APPROVED BY <u><i>W. A. Gressett</i></u>	TITLE <b>OIL AND GAS INSPECTOR</b>	DATE <b>OCT 7 1971</b>
CONDITIONS OF APPROVAL, IF ANY:		