

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN ☐ LIFICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0154766

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> Dry Hole		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR McClellan Oil Corporation		8. FARM OR LEASE NAME BAR-J Federal	
3. ADDRESS OF OPERATOR P. O. Box 848, Roswell, New Mexico 88201		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 680' FNL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Haystack Cisco	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15-T6S-R27E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4090' GR	12. COUNTY OR PARISH Chaves	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pursuant to verbal instructions this test was plugged and abandoned as follows:

Set 5½" cast iron bridge plug at 6000' and dumped 35' cement on top of plug.

RECEIVED

Set 30 sacks at 3050'.

MAR 16 1976

Set 35 sacks at 2482' and 1440'.

Set 10 sack plug at surface.

O. C. C.
ARTESIA, OFFICE

A dry hole marker will be installed and the location cleaned and returned to original condition as near as possible. You will be notified when this location has been cleaned and is ready for inspection.

RECEIVED

SEP-11-1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Lisa Taylor TITLE Agent DATE 9/4/75

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: