

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0154766

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

RECEIVED

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

McClellan Oil Corporation

SEP 9 1975

8. FARM OR LEASE NAME

BAR-J Federal

3. ADDRESS OF OPERATOR

P. O. Box 848, Roswell, New Mexico 88201 D. C. C.

9. WELL NO.

2

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.)  
At surface

10. FIELD AND POOL, OR WILDCAT

Haystack Cisco

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15-T6S-R27E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4090' GR

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON\*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT\*

☐

(Other) Well Testing

☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 8/12: Moved in Permian Basin Casing Pullers unit and equipment to test well.
- 8/13: Bled well down, broke wellhead down, ran 192 joints tubing with packer, hooked up well head, prep to swab well.
- 8/14: Swabbed well and kicked off flowing.
- 8/15: Opened well up and started flowing. Closed well in to run bottom hole pressure.
- 8/16: Bled well down and ran bottom hole pressure tool.
- 8/17: Well testing under direction of Larry Davis, gas testing engineer.
- 8/18: Determined well not commercial. Decision made to plug and abandon.

RECEIVED  
SEP - 5 1975  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Leis Taylor

TITLE

Agent

DATE

9/4/75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

SEP 8 1975  
H. L. BECKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side