

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TWO COPIES
(Other Instructions on reverse side)Form approved
Budget Bureau No. 42-R-424

5. LEASE DESIGNATION AND SERIAL NO.

NM Q154766

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BAR-J Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Haystack Cisco

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15-T6S-R27E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole MAY 5 1981
2. NAME OF OPERATOR McClellan Oil Corporation / O. C. D.
3. ADDRESS OF OPERATOR P. O. Box 848, Roswell, New Mexico 88201 ARTESIA, OFFICE
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660
680' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4090' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Pursuant to verbal instructions this test was plugged and abandoned as follows:

Set 5½" cast iron bridge plug at 6000' and dumped 35' cement on top of plug.

Set 30 sacks at 3050'.

Set 35 sacks at 2482' and 1440'.

Set 10 sack plug at surface.

A dry hole marker will be installed and the location cleaned and returned to original condition as near as possible. You will be notified when this location has been cleaned and is ready for inspection.

RECEIVED

SEP - 5 1975

U. S. GEOLOGICAL SURVEY
Agent ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent ARTESIA, NEW MEXICO

DATE

9/4/75

(This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 1 1981

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side