

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

**O. C. C.**  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-66

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-2509 & K-6023

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Read & Stevens, Inc.	Citgo - State "Com"
3. Address of Operator	9. Well No.
P. O. Box 2126, Roswell, New Mexico 88201	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>O</u> <u>990'</u> FEET FROM THE <u>South</u> LINE AND <u>1650'</u> FEET FROM	Buffalo Valley Penn Und
THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>14 South</u> RANGE <u>27 East</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3496.4' GL	Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Received permission to P&A via telephone from Mr. Bill Gressett.
- Set plugs as follows: TD 8475
  - 35 sx. cement plug 8200' to 8100'.
  - 35 sx. cement plug 7021' to 6921'.
  - 35 sx. cement plug 5146' to 5046'.
  - 35 sx. cement plug 2730' to 2630'.
  - 35 sx. cement plug 1673' to 1573'. (8-5/8" shoe @ 1623')
  - 50 sx. cement plug Stub of 8-5/8" casing 50' in and 50' out.
  - 70 sx. cement plug 380' to 280'. (12-3/4" shoe @ 330')
  - 15 sx. cement plug 10' to 0'
- Install regulation marker.
- Hole full of good mud before plugging began.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carl Schellinger TITLE Agent DATE July 13, 1972

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JUL 18 1972

CONDITIONS OF APPROVAL, IF ANY: