

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

**JUL 18 1972**

**O. C. C.**  
**ARTESIA, N.M.**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2509 & K-6623
7. Unit Agreement Name -----
8. Farm or Lease Name Citgo - State "Com"
9. Well No. 1
10. Field and Pool, or Wildcat Buffalo Valley Penn Und
12. County Chaves

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Read & Stevens, Inc.
3. Address of Operator P. O. Box 2126, Roswell, New Mexico, 88201
4. Location of Well UNIT LETTER <u>O</u> , <u>990'</u> FEET FROM THE <u>South</u> LINE AND <u>1650'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>14-S</u> RANGE <u>27-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3508' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Hole full of good mud. 60 Vis.
- Set plugs as follows:
  - 35 sx. cement plug 8200' to 8100'.
  - 35 sx. cement plug 7020' to 6920'.
  - 35 sx. cement plug 5150' to 5050'.
  - 35 sx. cement plug 2730' to 2630'.
  - 35 sx. cement plug 1670' to 1570'.
  - Cut 8-5/8" casing @ 644'.
  - 50 sx. cement plug 694' to 594'.
  - 70 sx. cement plug 379' to 279'.
  - 15 sx. cement plug 10' to 0'.
- Installed regulation marker and cleaned location.
- Will notify when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Schilling TITLE Agent DATE July 13, 1972

APPROVED BY John McManis TITLE OIL AND GAS INSPECTOR DATE APR 22 1974

CONDITIONS OF APPROVAL, IF ANY: