

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

SEP 28 1973

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-4318-2
7. Unit Agreement Name
8. Farm or Lease Name State 16
9. Well No. 1
10. Field and Pool, or Wildcat Und. Haystack Sil.-Dev.
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS O. C. C.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEEPER.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Read & Stevens, Inc. ✓

3. Address of Operator
P. O. Box 2126, Roswell, New Mexico 88201

4. Location of Well
UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 16 TOWNSHIP 6-S RANGE 27-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4114.3 GR, 4123.5 RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug well as follows:

Cut 5 1/2" casing at approximately 4660' and pull.
Fill hole with good mud.
Set cement plug over perfs 6424-6430, 6382-6388 and 6196-6204. 355X *
Set 35 sack cement plug at 5 1/2" casing stub.
Set cement plug 2400-2500. 355X *
Set cement plug 1380-1480 (at base of 8 5/8" casing). 355X *
Set surface plug.
Install regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carla Schellinger TITLE Agent DATE 9/26/73

APPROVED BY W. A. Grasse TITLE OIL AND GAS INSPECTOR DATE OCT 1 1973

CONDITIONS OF APPROVAL, IF ANY:
* as noted above

Notify N.M.O.C.C. in sufficient time to witness
Plugging starting w/ plug @ 5 1/2" stub