

Form 3160-5  
(November 1983)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-0333227	
2. NAME OF OPERATOR McClellan Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P O Drawer 730, Roswell, NM 88202-0730		7. UNIT AGREEMENT NAME North King Camp Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FSL & 660 FEL		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. 11	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3742' GR		10. FIELD AND POOL, OR WILDCAT Chaves Undes Atoka (Gas)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA Sec. 35-T13S-R29E	
		12. COUNTY OR PARISH Chaves	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5-24-93 Tubing parted @ 6351'.  
5-24-93 Set 4½ cement retainer @ 6190' and squeeze with 50 sacks cement  
Load Hole with mud  
Cut and Pull 4½" casing from 6169'  
Spotted 25 sacks cement @ 4½ stub 6190', W.O.C. Tag plug @ 6112'.  
Spotted 30 sacks cement @ 5265'  
Spotted 30 sacks cement @ 3820'  
Spotted 45 sacks cement @ 2490', 8 3/8 shoe W.O.C. Tag plug @ 2338'.  
Spotted 30 sacks cement @ 1500'  
Spotted 30 sacks cement @ 334'  
Spotted 15 sacks cement @ 60' to surface.  
5-26-93 Set P & A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

Mark McClellan

TITLE

President

DATE

12-01-93

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

DEC 6 1993

\*See Instructions on Reverse Side