



PETROLEUM EXPLORATION / INVESTMENT / DRILLING / PRODUCTION  
600 AMARILLO PETROLEUM BUILDING / AMARILLO, TEXAS 79101

**THE HARLOW CORPORATION**

PHONE (806) 372-7381 **RECEIVED**

OCT 20 1980

O. C. D.  
ARTESIA, OFFICE

October 17, 1980

Mr. W. A. Gressett, District Supervisor  
Energy and Mineral Department  
Oil Conservation Commission  
P.O. Drawer DD  
Artesia, NM 88210

Re: O'Brien Fee '19'-3 ✓  
(3-M-19-8-29)

Dear Mr. Gressett:

Our treatment of Jan. 10, 1980, the third one, was not successful and we have not treated anymore. The first two treatments showed oil at first but soon changed to all water. Both of these were relatively large treatments and this may be our trouble. All zones were treated together.

We anticipate that we will isolate the zone 2675-78 and treat and test it individually. We should be able to get to this in the near future.

Yours truly,

THE HARLOW CORPORATION

*W.B. LaFon*  
W.B. LaFon  
Production Engineer

WBL/ps