

CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
L-5026

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1.  OIL WELL  GAS WELL  OTHER  Dry

2. Name of Operator  
McClellan Oil Corporation

3. Address of Operator  
P. O. Drawer 730, Roswell, New Mexico 88201

4. Location of well  
UNIT LETTER H 1980 FEET FROM THE North LINE AND 880 FEET FROM  
THE East LINE, SECTION 6 TOWNSHIP 4-S RANGE 26-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3904' G.L.

7. Unit Agreement Name

8. Form or Lease Name  
Camp State

9. Well No.  
1

10. Field and Pool, or Wildcat  
Wildcat

12. County  
Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTERN CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This test was perforated 4045-4346 at various intervals as previously reported. WLBP set at 4260 & 4135'. Tested to 2000 lbs. Propose to P&A as follow as per verbal instruction this date from Bill Gressett

1. Pump 25 sx plug to 4135 (to WLBP)
2. Pull 4½" casing from approximately 3750' (T. Cement 3790). Pump 100' plug in and out of 4½" casing stub. *+tag*
3. 100' plug 1429-1529 (8-5/8" casing set at 1479' circulated) *+tag*
4. 100' plug 1850-1950 (Glorieta)
5. Set dry hole marker and restore surface
6. Heavy mud will be pumped between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe J. McClellan TITLE Operator DATE 8/08/80

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE AUG 12 1980

CONDITIONS OF APPROVAL, IF ANY:  
Notify N.M.O.C.C. in sufficient time to w/ plugging